

# Some g-code examples and recipes

G-code while being universal machine control language has various flavors and capabilities. Below section is dedicated to speed up manual machine control with simple commands.

## Move motors

There are two basic linear motion commands G0 and G1. Both are generally the same just G0 uses default max speed constant from configuration. Examples (assume linear actuator is connected):

Command	Explanation
<code>G0 X100</code>	Move X axis to absolute position 100mm
<code>G1 X0 F100</code>	Move X axis to 0 position at speed 100mm/min

## Control GPIO pins

GRBL is designed for CNC machines and IO pins are used to make sense. Pin description is provided here, but for actual functionality source code should be inspected.

Command	Explanation
<code>M7</code>	MIST = ON
<code>M8</code>	FLOOD = ON
<code>M9</code>	MIST = OFF, FLOOD = OFF

Command	Explanation
<code>M3</code>	Set clockwise spindle rotation
<code>S300</code>	Set spindle control pin PWM duty cycle at 30% (max S = 1000)
<code>M4</code>	Set counter clockwise spindle rotation
<code>M5</code>	Turn spindle off

## Motor homing

After powering controller on it does not know motor position, thus it should be driven to home reference position

Command	Explanation
<code>\$HX</code>	Initialize X axis

## Read controller status

Almost any time controller status can be read with command `?`. It will report motor status (Idle/Run), actual positions and some other info.

Command	Output
<code>?</code>	<code>&lt;Idle  MPos: 0.000, 90.000, 0.000, 0.000  Bf: 35, 254  FS: 0, 0&gt;</code>

## Read firmware version string

Functionality between versions will vary, some firmware versions or branches can have special functionality.

Command	Output
<code>\$I</code>	<code>[ VER: 1.1f- SCE2. 20200405: ]</code> <code>[ OPT: VMZHL, 35, 254 ]</code> <code>ok</code>

## Probing

Firmware allows use of touch trigger probes. Moves down Z axis and stops on when probe pin is triggered, then reports collision point.

Command	Explanation and Output
<code>G38.2 F100 Z-100</code>	Move down Z axis until PROBE pin is triggered <ul style="list-style-type: none"><li>F - Speed</li><li>Z - Target depth</li></ul> Replies with <code>[ PRB: 1.503, 0.000, -22.860, 0.000: 1 ]</code>

## Idle / wait

Idle command is useful for certain operations where controller needs to wait and do nothing (for example wait till spindle speeds up).

Command	Explanation
<code>G4 P1.5</code>	Wait 1.5 seconds, reply with <code>ok</code> when done

## Read write parameters

Controller has quite a few parameters that can be set in EEPROM. See original description [here](#).

Command	Explanation and Output
<code>\$\$</code>	Read parameters <code>\$0=6</code> <code>\$1=255</code> <code>\$2=0</code> <code>\$3=31</code> <code>...</code> <code>\$132=360.000</code> <code>\$133=360.000</code> <code>ok</code>
<code>\$132=100.00</code>	Set single paramter with the new value  Replies with <code>ok</code>

## Extra commands

Extra GPIO control commands used in motorized zoom lenses (L084, L0117, ...).

Command	Explanation and Output
<code>M113 Px</code>	Control GPIO IO3, replies with <code>ok</code>
<code>M114 Px</code>	Control GPIO IO4, replies with <code>ok</code>
<code>M115 Px</code>	Control GPIO IO5, replies with <code>ok</code>
<code>M116 Px</code>	Control GPIO IO6, replies with <code>ok</code>
<code>M117 Px</code>	Control GPIO IO7, replies with <code>ok</code>
<code>M120 Px</code>	Control GPIO LIM_EN, replies with <code>ok</code>

Where X is 0 or 1

---

Revision #9

Created 22 September 2020 18:07:30 by Saulius

Updated 2 March 2025 07:20:13 by Saulius